

SSO Summary Report

For overflows between: 12/31/09 And 1/1/11

<i>Overflow Service Area / ID</i>	<i>Municipality</i>	<i>Facility</i>	<i>Date Began</i>	<i>Date Ended</i>	<i>Duration (hours)</i>	<i>Volume Gallons</i>	<i>Receiving Water</i>	<i>Cause</i>	<i>POTW</i>
106	Town of Dewitt	Town sewer on Wedgewood Terrace Drive	01/07/2010	01/07/2010	1.75	100	Basement of House # 300.	Root intrusion Wedgewood Terrace.	Metropolitan Syracuse
107	Town of Geddes	Town of Geddes owned sewer	01/18/2010	01/18/2010	7.50	100	Harbor Brook	Rocks and debris resulted in an eight inch sanitary sewer main line backup.	Metropolitan Syracuse
108	Town of Cicero	County Owned Trunk Sewer	01/25/2010	01/25/2010	2.00	5	Basement of 5804 Sutton Drive.	Grease build up in ten inch County owned trunk sewer, restricted flow during wet weather event.	Oak Orchard
110	Town of Camillus	Town of Camillus owned sewer	02/08/2010	02/08/2010	1.75	50	Basement 105 Cloudview Circle	Heavy grease build up in town owned eight- inch SDR 35 residential sanitary sewer.	Metropolitan Syracuse
111	Town of Cicero	MH005604	02/22/2010	02/22/2010	0.75	225	Mud Creek	Partial blockage in eight inch Town owned sewer caused by either grease or industrial generated organic waste, in conjunction with high flows.	Oak Orchard
112	Town of Camillus	Town of Camillus Sewer	02/27/2010	02/27/2010	2.67	300	Basements 302, 304 Farmington Drive	Root intrusion, debris and grease caused sewer main backup in a town owned 8" clay sewer.	Metropolitan Syracuse
113	Town of Cicero	Town of Cicero owned Winterhaven pump station	03/01/2010	03/01/2010	2.25	1,000	Drainage swale and ground area around station	No power to the pumps. Control fuses in cabinet were blown.	Brewerton
114	Town of Onondaga	Fuller Farms Pump Station Force Main	03/02/2010	03/03/2010	13.00	100	Harbor Brook	Forceman was previously repaired and the repair failed.	Metropolitan Syracuse

Library Reference 4.4

Overflow ID	Service Area / Municipality	Facility	Date Began	Date Ended	Duration (hours)	Volume Gallons	Receiving Water	Cause	POTW
115	Town of Onondaga	Fuller Farms Pumpstation	03/10/2010	03/10/2010	0.25	25	Ground	Town of Onondaga owned two inch PVC forcemain was repaired approximately 15-20 feet away on 3/3/10. During previous repair, disturbance of the pipe may have attributed to this failure.	Metropolitan Syracuse
117	Town of Onondaga	Hillbrook Detention Center	03/30/2010	03/30/2010	3.50	50	Ground	Ten-inch clay tile pipe running from facility to main sewer was blocked by roots.	Metropolitan Syracuse
118	Town of Cicero	Town of Cicero Sewer	03/31/2010	03/31/2010	1.00	100	Basement 5685 Williamson Parkway	Grease accumulation in eight inch asbestos cement sewer caused sewer to surcharge and backup into basement.	Oak Orchard
119	Village of Liverpool	Village of Liverpool Sewer	04/19/2010	04/19/2010	1.00	5	Basement of 110 Tamarack St.	Eight-inch clay sewer surcharged possibly due to root intrusion.	Metropolitan Syracuse
122	Town of Salina	Storm Sewer	05/23/2010	05/23/2010	2.33	1,000	Ley Creek	Town of Salina owned eight-inch clay sewer surcharged possibly due to root intrusion and grease build up. Flow exited sanitary manhole and entered storm sewer catch basin which is tributary to ley creek.	Metropolitan Syracuse
124	Town of Cicero	6030 East Taft Rd.	06/05/2010	06/07/2010	41.50	5,600	Ground	Contractor excavating for roadway drainage work broke sewer lateral to 28 unit apartment complex.	Oak Orchard
123	Town of Cicero	9549 Neva Lane	06/07/2010	06/07/2010	1.45	50	Basement	Grease build up in Town of Cicero owned 8-inch asbestos cement sewer line.	Brewerton

Library Reference 4.4

<i>Overflow ID</i>	<i>Service Area / Municipality</i>	<i>Facility</i>	<i>Date Began</i>	<i>Date Ended</i>	<i>Duration (hours)</i>	<i>Volume Gallons</i>	<i>Receiving Water</i>	<i>Cause</i>	<i>POTW</i>
128	Town of Onondaga	1320 Grand Avenue	06/28/2010	06/28/2010	1.80	75	Basement 1320 Grand Avenue	Malfunction of both pumps at Hillcrest pumpstation, causing backup in gravity sewer that leads to the pumping station.	Metropolitan Syracuse
129	Town of Dewitt	Town of Dewitt Sewer	08/06/2010	08/06/2010	3.50	1,000	Storm Water Retension Pond	Gravel and grit build up in Town of Dewitt owned 8-inch clay tile sewer line partially blocked sewer.	Metropolitan Syracuse
130	Town of Geddes	Hillcrest Pumping Station 1320 Grand Ave	08/13/2010	08/13/2010	0.25	400	Harbor Brook	Pump 1 pump/electrical failure, pump 2 was taken out of service for variable frequency drive repair. Alarm was received at 4:48 PM, station was back on line approximately 5:20. Approximately 400 gallons of wastewater overflowed to Harbor Brook through the controlled diversion structure.	Metropolitan Syracuse
135	Town of Camillus	Manhole # 020835	08/22/2010	08/22/2010	2.50	1,000	Nine Mile Creek	Over flow from Town of Camillus owned manhole during period of heavy rain.	Metropolitan Syracuse
131	Town of Geddes	Westside Pumping Station outfall 068	08/22/2010	08/23/2010	22.00	2,200,000	Onondaga Lake	4.6 inches of rain between 07:00, 8/22/10 and 07:00 8/23/10.	Metropolitan Syracuse
132	Town of Salina	Manhole # 018437 on Garden City Drive	08/22/2010	08/23/2010	13.00	390,000	Ley Creek	4.6 inches of rain between 07:00, 8/22/10 and 07:00 8/23/10.	Metropolitan Syracuse
133	Town of Salina	Manhole # 000638 Young Avenue	08/22/2010	08/23/2010	10.00	300,000	Ley Creek	4.6 inches of rain between 07:00, 8/22/10 and 07:00 8/23/10.	Metropolitan Syracuse
134	Town of Salina	Ley Creek Pump Station	08/22/2010	08/23/2010	12.00	13,800,000	Ley Creek	4.6 inches of rain between 07:00, 8/22/10 and 07:00 8/23/10.	Metropolitan Syracuse

Library Reference 4.4

<i>Overflow ID</i>	<i>Service Area / Municipality</i>	<i>Facility</i>	<i>Date Began</i>	<i>Date Ended</i>	<i>Duration (hours)</i>	<i>Volume Gallons</i>	<i>Receiving Water</i>	<i>Cause</i>	<i>POTW</i>
136	Town of Geddes	Lakeside Forcemain	08/23/2010	08/23/2010	7.00	1,000	Ground	Eighteen inch forcemain deteriorated due to age and environmental conditions. Developed a hole under railroad tracks East of Gate 2 of the New York State Fairgrounds.	Metropolitan Syracuse
137	Town of Geddes	Lakeside Pump Station	08/23/2010	08/26/2010	63.50	1,140,000	Nine Mile Creek	Bypass Lakeside pump Station due to Onondaga County owned Lakeside Forcemain failure East of Gate #2 of the New York State Fairgrounds.	Metropolitan Syracuse
139	Town of Camillus	Town of Camillus manhole	09/08/2010	09/08/2010	0.50	300	Ground	Town owned sewer line was partially plugged. Previous attempts to clean line were unsuccessful. While attempting to televisue line to determine cause of blockage, line became further blocked causing overflow.	Metropolitan Syracuse
146	Town of Salina	Ley Creek Pump Station outfall 084	09/30/2010	10/01/2010	5.50	763,000	Ley Creek	2.87 inches of rain from 5:00 AM 9/30 to 5:00AM 10/1/10 recorded at Hancock Field overloaded sanitary sewer system.	Metropolitan Syracuse
147	Town of Manlius	Town Owned Sewer @ Manor Dr. and Lee Terrace	09/30/2010	10/02/2010	31.25	937,500	Limestone Creek	4.22 inches of rain from 5:00 AM 9/30 to 5:00 AM 10/1/10 recorded at lakeport weather station.	Meadowbrook-Limestone
145	Town of Salina	Viking Place Manhole, Outfall 092	09/30/2010	09/30/2010	0.83	5,000	East Branch Bloody Brook	2.87 inches of rain from 5:00 AM 9/30 to 5:00AM 10/1/10 recorded at Hancock Field overloaded sanitary sewer system.	Metropolitan Syracuse
142	Town of Salina	Manhole # 018437 on Garden City Drive	09/30/2010	10/01/2010	6.25	187,500	Ley Creek	2.87 inches of rain from 5:00 AM 9/30 to 5:00AM 10/1/10 recorded at Hancock Field, overloaded sanitary sewer system.	Metropolitan Syracuse

Library Reference 4.4

<i>Overflow Service Area / ID</i>	<i>Municipality</i>	<i>Facility</i>	<i>Date Began</i>	<i>Date Ended</i>	<i>Duration (hours)</i>	<i>Volume Gallons</i>	<i>Receiving Water</i>	<i>Cause</i>	<i>POTW</i>
158	Town of Geddes	West Side Pumping Station out fall # 068	12/01/2010	12/01/2010	1.00	76,000	Onondaga Lake	1.36" of rain. Alarm signal failure, potentially due to weather and power surges. High wet well alarm was not received at Metro Board to have personnel respond to station.	Metropolitan Syracuse
153	Town of Salina	Manhole # 000638 Young Avenue	12/01/2010	12/01/2010	3.50	105,000	Ley Creek	1.36" of rain. National Grid Transmission Line Power Failure. Onondaga county owned Ley Creek Pumping Station was without power from 10:10 AM to 1:23PM. Resulting in Tributary sewer lines backing up.	Metropolitan Syracuse
154	Town of Salina	Mh 018262 Boulevard St. Mattydale	12/01/2010	12/01/2010	3.00	90,000	Ley Creek	1.36" of rain. National Grid Transmission Line Power Failure. Onondaga county owned Ley Creek Pumping Station was without power from 10:10 AM to 1:23PM. Resulting in Tributary sewer lines backing up.	Metropolitan Syracuse
155	Town of Salina	Ley Creek Pump Station outfall 084	12/01/2010	12/01/2010	5.33	736,000	Ley Creek	1.36" of rain. National Grid Transmission Line Power Failure. Onondaga county owned Ley Creek Pumping Station was without power from 10:10 AM to 1:23PM. Resulting in Tributary sewer lines backing up.	Metropolitan Syracuse
156	Town of Salina	Outfall 091 Ley Creek Pump Station	12/01/2010	12/01/2010	3.00	2,750,000	Ley Creek	1.36" of rain. National Grid Transmission Line Power Failure. Onondaga county owned Ley Creek Pumping Station was without power from 10:10 AM to 1:23PM. Resulting in Tributary sewer lines backing up.	Metropolitan Syracuse

Library Reference 4.4

<i>Overflow ID</i>	<i>Service Area / Municipality</i>	<i>Facility</i>	<i>Date Began</i>	<i>Date Ended</i>	<i>Duration (hours)</i>	<i>Volume Gallons</i>	<i>Receiving Water</i>	<i>Cause</i>	<i>POTW</i>
157	Town of Salina	433 and 435 Kirsh Ave. MattyDale	12/01/2010	12/01/2010	3.75	50	Basements around floor drain	1.36" of rain. National Grid Transmission Line Power Failure. Onondaga county owned Ley Creek Pumping Station was without power from 10:10 AM to 1:23PM. Resulting in Tributary sewer lines backing up.	Metropolitan Syracuse
152	Town of Salina	Outfall 087 on Garden City Drive	12/01/2010	12/01/2010	4.08	122,000	Ley Creek	1.36" of rain. National Grid Transmission Line Power Failure. Onondaga county owned Ley Creek Pumping Station was without power from 10:10 AM to 1:23PM. Resulting in Tributary sewer lines backing up.	Metropolitan Syracuse

CSO Summary Report

For overflows between: 12/31/09 And 1/1/11

Overflow ID	Service Area / Municipality	Facility	Date Began	Date Ended	Duration (hours)	Volume Gallons	Receiving Water	Cause	POTW
109	City of Syracuse	017 Hoefler Street	02/05/2010	02/05/2010	1.33	1,000	Harbor Brook	Blockage in transition from 30-inch combined sewer to 8- inch regulator pipe.	Metropolitan Syracuse
116	City of Syracuse	CSO Outfall 016	03/24/2010	03/24/2010	0.33	95,000	Harbor Brook	Eight inch City of Syracuse water main broke during backfill operations of the Harbor Brook Intercepting Sewer Replacement Project. Potable water entered catch basins, manholes and exposed piping.	Metropolitan Syracuse
120	City of Syracuse	CSO #032 Tully Street	04/30/2010	04/30/2010	1.00	200	Onondaga Creek	Partial blockage in transition from 24-inch combined sewer to 8- inch regulator pipe.	Metropolitan Syracuse
121	City of Syracuse	CSO # 066 Maltbie Street	05/06/2010	05/06/2010	2.00	1,000	Onondaga Creek	Half inch steel cable with rags and debris collected on it partially blocked the 18-inch mainline sewer.	Metropolitan Syracuse
125	City of Syracuse	CSO 011 Gifford Street	06/18/2010	06/18/2010	0.50	250	Harbor Brook	Partial blockage in transition from 24-inch combined sewer to 8-inch regulator pipe.	Metropolitan Syracuse
127	City of Syracuse	CSO 066 Maltbie and Evans Street FCF	06/23/2010	06/23/2010	0.50	250	Onondaga Creek	Partial blockage in transition from 36-inch combined sewer to 16-inch regulator pipe.	Metropolitan Syracuse
126	City of Syracuse	CSO 011 Gifford Street	06/23/2010	06/23/2010	1.00	300	Harbor Brook	Partial blockage in transition from 24-inch combined sewer to 8-inch regulator pipe.	Metropolitan Syracuse